


## Resistance thermometer Pt 100 with integrated measuring transmitter



### Resistance thermometer Pt 100 with integrated measuring transmitter

|                                |                                  |
|--------------------------------|----------------------------------|
| <b>Resistance thermometer:</b> | Pt 100 Class A according IEC 751 |
| <b>Connection:</b>             | M 12x1                           |
| <b>Measuring Range:</b>        | - 50° up to +400°C               |
| <b>Diameter:</b>               | 2,0 mm                           |
| <b>Length:</b>                 | 100 mm                           |

### Measuring Transmitter

|                         |                        |
|-------------------------|------------------------|
| <b>Plastic Housing:</b> | Dimensions: 55 x 15 mm |
| <b>Connection:</b>      | M 12x1                 |
| <b>Measuring range:</b> | - 50°C up to +400°C    |
| <b>Accuracy:</b>        | +/- 0,2°C              |
| <b>Voltage Output:</b>  | 4... 20 mA             |
| <b>Voltage supply:</b>  | 24 V                   |